



Druckeinheiten / pressure units

10 bar = 10.000 mbar	1 bar = 1.000 mbar	0,1 bar = 100 mbar	0,01 bar = 10 mbar
10 bar = 1.000 kpa	1 bar = 100 kpa	0,1 bar = 10 kpa	0,01 bar = 1 kpa
10 bar = 100 m WS	1 bar = 10 m WS	0,1 bar = 1 m WS	0,01 bar = 0,1 m WS
10 bar = 1 mpa	1 bar = 0,1 mpa	0,1 bar = 0,01 mpa	0,01 bar = 0,001 mpa
10 bar = 0,68948 psi	1 bar = 0,068948 psi	0,1 bar = 0,0068948 psi	0,01 bar = 0,00068948 psi

Temperatureinheiten / temperature units

Temperatur in °C	Temperatur in °F		Temperatur in °F	Temperatur in °C
temperature in °C	temperature in °F		temperature in °F	temperature in °C
			- 300	= - 184,44
- 250	= - 418		- 250	= - 156,67
- 200	= - 328		- 200	= - 128,89
- 150	= - 238		- 150	= - 101,11
- 100	= - 148		- 100	= - 73,33
- 50	= - 58		- 50	= - 45,56
0	= 32		0	= - 17,78
50	= 122		50	= 10,00
100	= 212		100	= 37,78
150	= 302		150	= 65,56
200	= 392		200	= 93,33
250	= 482		250	= 121,11
300	= 572		300	= 148,89
350	= 662		350	= 176,67
400	= 752		400	= 204,44
450	= 842		450	= 232,22
500	= 932		500	= 260,00